


1/24 FIG. 1




^{2/24} FIG. 2




^{3/24} FIG. 3




4/24 FIG. 4




5/24 FIG. 5




6/24 FIG. 6




^{7/24} FIG. 7



8/24 FIG. 8




9/24 FIG. 9




10/24


FIG. 10



11/24 FIG. 11




12/24 FIG. 12




13/24


FIG. 13




14/24 FIG. 14



15/24 FIG. 15




16/24 FIG. 16




17/24

FIG. 17




18/24 FIG. 18




19/24


FIG. 19



^{20/24} FIG. 20




^{21/24} FIG. 21




22/24

FIG. 22



23/24

FIG. 23



24/24

Reference numerals in the drawings

- 1 Brushless DC motor
- 2 Stator coil
- 3 Magnet rotor
- 3a Pole anisotropic magnet
- 4 Magnetic flux sensor
- 5 Controller
- 6 Inverter circuit
- 7 Current waveform controller
- 8 DC voltage converter
- 9 Rectifier
- 10 Stator
- 12 Magnetic flux density synthesizer
- 13 Smoothing capacitor
- 14 DC voltage changer
- 15 AC source coupler
- 15a Strong output terminal
- 15b Weak output terminal
- 16 Coupling sensor
- 24 Switch
- 25 PWM controller
- 26 Duty instructing means
- 30 Current sensor
- 31 Current controller
- 32 Set current changer
- 33 Current instructing means
- 34 Rotary signal output means
- 39 Rpm range sensor
- 40 Current instructing means
- Q1 Q6 Switching element